



english



# Colour fastness testing products **catalogue**

*For your investment in quality*

- SDC Multifibre DW Fabric
- SDC Standard Test Fabrics
- SDC Light Fastness Fabric
- SDC Detergents and Auxiliaries
- SDC Testing Chemicals
- SDC Martindale Consumables
- SDC Assessment Aids
- SDC Phenolic Yellowing Products
- Miscellaneous Products

07  
issue

[www.sdcenterprises.co.uk](http://www.sdcenterprises.co.uk)

The SDC logo is displayed in a large, bold, black font. It is positioned in the upper left quadrant of the page, partially overlapping a background image of a computer keyboard.

# Assessment Aids

## Grey Scale for Change in Colour

The grey scale consists of nine pairs of non-glossy neutral grey coloured chips which illustrate the perceived colour differences. These give a corresponding fastness rating of 5, 4-5, 4, 3-4, 3, 2-3, 2, 1-2, and 1.

They are used in the assessment of colour change occurring in fastness tests as described in ISO 105-A02.

They are also essential in the grading of light fastness tests when using the light fastness standards.

## Grey Scale for Staining

The grey scale consists of nine pairs of non-glossy grey and white coloured chips which illustrate the perceived depth of staining.

They give a corresponding fastness rating of 5, 4-5, 4, 3-4, 3, 2-3, 2, 1-2, and 1.

They are used to assess the amount of staining occurring on adjacent undyed fabrics during fastness tests. Their use is described in ISO 105-A03.

## Fluorescence Suppressor

This is a laminated glass plate used to overcome optical interference from Fluorescent brightening agents on textile, leather and paper. This is essential when grading assessment is being carried out on an item containing Fluorescent brightening agents.

The laminated glass plate is supplied in a protective box.





# Certificates of Conformity

**FREE OF CHARGE**

**CERTIFICATES & MSDS SHEETS AVAILABLE ONLINE**

For further information on this service please go to [www.sdcesecure.co.uk](http://www.sdcesecure.co.uk)

## SDC Assessment Aids

3305	SDC Grey Scales for Assessing Change in Colour	Each
3355	SDC Grey Scales for Assessing Staining	Each
3405	SDC Standard Depths	Each
3605	SDC Humidity Control Fabric	Per pattern
3716	SDC Assessment Mask Type C	Each
3810	SDC Fluorescence Suppressor (Laminate Plate)	Each

